


Connecting diagram 0301-1-0049



CONNECTION OPTIONS:

L1	L2	L3	PE	Protection device	Join together	Winding connection
U1	V1	W1	PE	TK , TK	[U2.V2,W2]	STAR (Y) - high voltage (STANDARD)
U1	V1	W1	PE	TK , TK	[U1,W2]; [V1,U2]; [W1,V2]	DELTA (Δ)- low voltage

* CHANGING OF ROTATION DIRECTION BY INTERCHANGING OF 2 PHASES!

* TEMPERATURE MONITORS (TK) BUILT IN TO THE WINDING SERVE AS MOTOR CUT-OUT SWITCH AND MUST BE CONNECTED TO THE OUTSIDE CONTROL UNIT!